



Diesel Parts

——Higher Pressure Pump



Tianjin Wode Electrical Co., Ltd.

B-1-1703, Rome Garden, YongAn Rd. Hexi Dist. Tianjin, China

web-site: www.tj-wode.com e-mail: twt@tj-twt.com

Tel: 0086-22-23286383 Fax: 0086-22-83863296

O.E.M names and numbers are used for reference purpose only.



78 6801

Replacing 03C127026Q
133071

Servicing Audi A1 A3



78 6802

Replacing 06H127025N
0261520347


Servicing Audi A3 A4 A5 TT



78 6803

Replacing 06J127025C
133070

Servicing Audi A4 A5 A6 A8 Q5 TT
VW Tiguan



78 6804

Replacing 06E127025M
133069


Servicing Audi A6L A5 A8 A8L



78 6805

Replacing 07L127026AB

Servicing Audi A4 Q5 S5 A7 Touareg
3.0TFSI



78 6806

Replacing 06F127025F
133064


Servicing Audi A6L A1 A3 A4



78 6807

Replacing 06E127025AB
133063


Servicing Audi A4 A6



78 6808

Replacing 03H127025
133073


Servicing Audi Q7 VW Passat
Touareg



78 6809

Replacing 03H127025C
133074


Servicing Audi Q7 Porsche Cayenne
Touareg



78 6810

Replacing 03H127025E
133075


Servicing Audi Q7 VW Passat



78 6811

Replacing 03H127025M
133076


Servicing VW CC Passat B6 B7



78 6812

Replacing 03H127025N
133077

Servicing Audi A4 A5 A6 A8 Q7
Poesche Cayenne Touareg



78 6813

Replacing 079127026AA
133068

Servicing Audi R8 VW Phaeton
Touareg



78 6814

Replacing 079127025AC
133065


Servicing



78 6815

Replacing 079127026AC
133066

Servicing Audi A5 A6 A8 Q7



78 6816

Replacing 079127026AB
133087

Servicing Audi A4 A6 A8 Q7



78 6817

Replacing 079127025AF
133086


Servicing Audi A4 A6 A8 Q7



78 6818

Replacing 03C127025T
133062

Servicing Golf Jetta Touran



78 6819

Replacing 03C127025R
133060


Servicing Audi A3 Golf Jetta Passat
Touran



78 6820

Replacing 06F127025A
133061

Servicing Audi A3 2.0 FSI Golf 2.0
FSI Touran 2.0 FSI



78 6826

Replacing 948110316HX

Servicing PORSCHE S4.8L GTS4.8L



78 6827

Replacing 9A111031506

Servicing PORSCHE



78 6828

Replacing 94811031502

Servicing PORSCHE Cayenne GTS
4.8L Panamera 4.8L



78 6829

Replacing 94011021572

Servicing PORSCHE


78 6836

Replacing 12641740
HM10007

Servicing BUICK


78 6837


Replacing 12641847
HM10008

Servicing GM Chevrolet Regal
Lacross


78 6840


Replacing 2780700601
0261520119

Servicing Mercedes-benz CL500
CL63 CLS500 CLS63 E500
E63AMG GL500 S500
S63AMG


78 6841


Replacing 13517610761
0261520131

Servicing BMW 3 435 535 6 X3 X5
X6


78 6842

Replacing BM5G9D376BB
0261520140

Servicing FORD C-MAX II FIESTA
VI FOCUS III


78 6843

Replacing 13517595339
0261520143

Servicing BMW X5 E70 X6 E71 E72
5 6 7 F01 F02F03 F04


78 6844


Replacing 13517584461
0261520147

Servicing BMW 1 F21 3 F34 4 F32
F33 F82 F83 ZE E89 X1
E84


78 6845


Replacing AG9E9D376AB
0261520152

Servicing Volvo S60 S80 V60 V70 XC60
FORD FOCUS III 2.0 GALAXY
(CK) 2.0 EcoBoost MONDEO
IV (BA7) 2.0 EcoBoost


78 6846


Replacing 2700700501
0261520212

Servicing Mercedes-benz A-CLASS
B-CLASS CLA Coupe


78 6847


Replacing 2780701101
0261520219

Servicing Mercedes-benz C-CLASS
E-CLASS E-CLASS Coupe


78 6848


Replacing 13518604229
0281520281

Servicing BMW 125i 220i 320i 328i
420i 428i 528i X1 X3 Z4


78 6849

Replacing 13518604231
0261520283

Servicing BMW 335i 435i 535i 640i
740Li X3 X4 X5 X6



78 6850

Replacing 13518605102
0261520289

Servicing MINI Copper Countryman
Paceman S Coupe



78 6851

Replacing 13517592429


Servicing MINI R55 Clubman R56
Hatch R58 Coupe



78 6852

Replacing 13517573436
9819938480

Servicing BMW Clubman Coupe
CITROEN C4 Coupe
Picasso I II DS5



78 6853

Replacing 13517616170

Servicing BMW 535i 640i 740Li X1
X3



78 6854

Replacing 2710703701

Servicing Mercedes-benz C-CLASS
E200 C200 SLK200