



Hydraulic Pump



Tianjin Wode Electrical Co., Ltd.

B-1-1703, Rome Garden, YongAn Rd. Hexi Dist. Tianjin, China

web-site: www.tj-wode.com e-mail: twt@tj-twt.com

Tel: 0086-22-23286383 Fax: 0086-22-83863296

O.E.M names and numbers are used for reference purpose only.



78 4016

Replacing A42X

Servicing UTB



78 4017

Replacing 5000787865
555224771

Servicing RENAULT



78 4124

Replacing 897147M92

Servicing Massey Ferguson 165 168
175 178 185 188 265 275
285 290 565 575 590 690
MF-4



78 4125

Replacing 3819972M91

Servicing Massey Ferguson MF-4



78 4128

Replacing 38.33.018
H8-01

Servicing UTB 650



78 4137

Replacing 3597706M91

Servicing MASSEY FERGUSON 174
184 194 362 365 372 375
382 390 398 390T



78 4138

Replacing 773126M92

Servicing MASSEY FERGUSON 135
148 230 240 250 35 35X



78 4139

Replacing 886821M94

Servicing MASSEY FERGUSON 133
135 140 148 155 158 165
185 188



78 4140

Replacing 1686765M91

Servicing MASSEY FERGUSON 133 135 140
158 165 168 175 178 185 188 230
240 250 265 275 285 290 550 565
575 590 595 675 690 1004 1080
1200 1250



91 6008

Replacing 0510665381
1175992

Servicing DEUTZ-FAHR FENDT



91 6009

Replacing 0510615318
02382915

Servicing FENDT,DEUTZ



91 6072

Replacing 052107T1

Servicing MF 200 265 275 283 290 298
250X 292 297 299 400 410 420
415 425 435 440 445 460 465
475 481 492 440

**91 6078**

Replacing 0510615333
01175656

Servicing DEUTZ FL912 FL913
DX3.10VC

**91 6079**

Replacing 0510665382
01176000

Servicing DEUTZ TRACTOR 10006
1006M/U 13006 8006 8006F/T
6807/A/C 7007/A /C7207/A
7807/A/C MF440

**91 6083**

Replacing 0510315307

Servicing

**91 6084**

Replacing 80255

Servicing RENAULT

**91 6085**

Replacing 5179728
VPK1040

Servicing FIAT 480 500 540 FORD
4635 LONG 310 350 360
445 460 510 560 610

**91 6086**

Replacing 0510715306

Servicing KHD

**91 6087**

Replacing 0510615322
2244926

Servicing DEUTZ FL912

**91 6088**

Replacing 800255

Servicing RENAULT

**91 6089**

Replacing 0511725028

Servicing MAN MAZ-103 107 203
206 216 232

**91 6090**

Replacing 0510615315

Servicing STEYR 8070 8080

**91 6093**

Replacing A18X
5179732
0510425324

Servicing Fiat

**91 6101**

Replacing C18X
5179724
0510425032

Servicing FIAT



91 6106

Replacing C25X
5179722
0510525046

Servicing FIAT



91 6108

Replacing A25X
5179730

Servicing FIAT 580 600 640 680 750 780
880 980 8035 8045 DAVID
BROWN 1200 1210 1212
AD4.55



91 6112

Replacing 87759440
E6NN3K514EA

Servicing FORD 2000 3000 4000
5000 7000



91 6127

Replacing 5135305
311547576

Servicing FIAT 1180 1380 1580 1880
FIATAGRI 115 130 140
160 180



91 6128

Replacing A31X
5129483

Servicing CASE 1394 1494 AD4.55T
FIAT 1000 1180 580 600 640
680 780 850 880 980
FIATAGRI 55 60 70 80 -90



91 6180

Replacing 0510615338
01174517

Servicing DEUTZ FAHR FENDT
Farmer 100



91 6185

Replacing C33

Servicing



91 6186

Replacing 5180275

Servicing FIATAGRI F100 F110 F115
F120 F130 F140 8065.05



91 6187

Replacing C42X
5179726
0510625063

Servicing CASE JX70 80 90U FIATAGRI
F100 F110 F115 F120 F130
F140 NEW HOLLAND 4635
4835 5635 6638 L60 L65 L75



91 6201

Replacing A42X
5129488
0510625362

Servicing FIAT 1380 1580 1880 CASE
1594 1698 AD6.55 FIATAGRI
115 130 140 160 180 55 60 70
80 90



91 6203

Replacing C31XPR
5180273
0510525059

Servicing FIAT 100-90 110
FIATAGRI 115 130 140
160 180 55 60 70 80 85 90